Q-292

SVE BULLETIN

SPECIAL VEHICLE ENGINEERING – BODY BUILDERS ADVISORY SERVICE

E-Mail via Website: www.FordBBAS.com (click "Contact Us")

Toll-free: (877) 840-4338

QVM Bulletin: Q-292 Date: 15,February,2019

Added Holes in Chassis Cab Frame Rails for After-market Hitch Installation

Models Affected: MY 2019 F350/450/550 Super-Duty Chassis Cabs (production phase in beginning February, 2019)

Description: **Four holes per rail, on the bottom flange, have been added to facilitate the installation of aftermarket hitches.**



Reverse Plan View

These holes have been added to help facilitate the installation of aftermarket trailer hitches. Aftermarket hitch load ratings are the responsibility of the aftermarket hitch manufacturer. The maximum trailer tow rating which is published in the RV & Trailer Tow Guide must never be exceeded.

These holes are being provided due to the larger aft-of-axle fuel tank that has inhibited the ability to drill holes in the lower flange of the frame rails for the installation of aftermarket hitches.